

VEHICLE INSPECTION REPORT

ST10XJC

Ford Fiesta 1.4 TDCi Van

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 30/07/2010

Year 2010

Mileage 125,505 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN WF0RXXGAJRAU73891

Body Style Car Derived Van

Keys 2

MOT Due Expired

Gearbox MANUAL

Gears 5

Steering Combi Standard Axle

Rear Suspension Steel

Tyres

NSF

NSR

OSF


OSR

Spare

Features


- Radio/CD
- Front electric windows
- Drivers airbag
- Central locking
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Dented
Over 30mm



2: Bumper Front
Chipped
Multiple Chips



3: Wing osf
Rusted
Over 5mm



4: Sill os
Rusted
Over 5mm



5: Qtr Panel osr
Dented
Over 30mm



6: Bumper Rear
Dented
Over 30mm



7: Qtr Panel nsr
Rusted
Over 5mm



8: Sill ns
Rusted
Over 5mm



9: Door nsf
Rusted
UpTo 5mm

10: Wing nsf
Rusted
Over 5mm

Interior

| Carpet Condition | | Average | | Upholstery Condition | | Average | |
|--------------------------|--|---------|--|--|--|---------|--|
| Seat Condition | | Average | | Odour | | No | |
| Engine Runs | | OK | | Gearbox 1st and Reverse Test | | OK | |
| Brakes | | OK | | Clutch Slip Test from Static | | OK | |
| Turbo Boosting | | OK | | Gearbox Static Gear Selection (engine running) | | OK | |
| Parking Brake | | OK | | No Excessive Smoking | | OK | |
| EML light illuminated | | OK | | Oil warning light illuminated | | OK | |
| Airbag light illuminated | | OK | | DPF light illuminated | | OK | |
| ABS light illuminated | | OK | | Service indicator light illuminated | | OK | |
| Windows | | OK | | Radio | | OK | |
| | | | | Steering | | OK | |