

VEHICLE INSPECTION REPORT

LN67WOA

Ford Transit 350 2.0 TDCI 130PS

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	To Follow
		Cap Id	37904
		Cap Code	FOTR20331R6DTM2 4 L

Details

Location	Bedford	GVW	3500kg	CAP Clean	£3,050.00
Reg. date	30/09/2017	Colour	GREEN	CAP Average	£2,550.00
Year	2017	VIN	WF0XXXTTGXHB72621	CAP Below	£1,925.00
Mileage	141,443 Miles Warranted	Body Style	Panel Van L3	Gearbox	MANUAL
Fuel Type	DIESEL	MOT Due	29/04/2027	Gears	6


WARNING LIGHT ON DASH SIDE LOADING DOOR


Tyres	
NSF	
NSR	
OSF	
OSR	
Spare	

Features


- Park assist camera
- Front electric windows

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Roof
Rusted
Over 5mm



3: Door nsr
Dented
With Paint Damage



4: Qtr Panel nsr
Dented
With Paint Damage



5: Qtr Panel Trim ns
Missing
Replace



6: Qtr Panel nsr
Dented
With Paint Damage



7: Qtr Panel nsr
Dented
With Paint Damage




8: Bumper Rear Moulding
Broken
Replace



9: Qtr Panel osr
Dented
Over 2 UpTo 10mm



10: Qtr Panel osr
Scratched
Over 25mm Thru Paint



11: Door osf
Chipped
Edge Chip



12: Door osf
Scratched
UpTo 25mm Thru Paint

Interior

Carpet Condition
Seat Condition

OK
OK

Upholstery Condition
Odour

OK
No

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	Fault	Service indicator light illuminated	OK